
SE Naranja Zone
Gold in Soils
Contours in ppb Au
Tertiary detachment fault zone
hematite-silica alteration zone
geologic contact with unit label
Jurassic(?) strike-slip fault
Placer zone
500 meters
Zone
Naranja
Placers
Dome Structure in Detachment Fault?
Higher Level Detachment Fault?
Southeast
Extension of
Naranja
Zone
3423000 N
3422000 N
363000 E
365000
South-Central Colibri Property and Locations of 1998, 2005, oles
(mapping by J. Nourse, 2005-08
datum = NAD27 Mexico)